Roger Maxie 255 Cedar Lane Critz, VA. 24082 (276) 692-4115 SouthernSoils255@yahoo.com

> Ben Maxie (757) 287-6238

thern Soils VA, LLC 255 Cedar Lane Critz, VA. 24082 (276) 692-4115

2/13/2024 Kirt Sharpe 4215 Chippenham Court Graham, NC. 27253

RE. Tax map # 4711-4-83

Dear Kirt Sharpe,

We have completed the preliminary soil evaluation study that was requested for the above referenced property. The purpose was to determine the suitability of the soil for the installation of a conventional subsurface drainfield (d/f). Please see the vicinity map enclosed for the soil boring locations.

A soil evaluation report is attached that generally describes the soils of the prospective drainfield. Please note, this is not a permit. In order to be permitted in the future, footprint may need to be surveyed or triangulated with two permanent measurement points.

At least three soils borings were done within the acceptable area with a soil auger and the corners were flagged on contour. The soils in this area are suitable for a subsurface, conventional sewer system in the flagged area. Care must be taken to protect this proposed area from damage. The potential gallons per day (GPD) for this tract has been determined by soil and area suitability, and the site has a two bedroom/300 gallons per day gravelless footprint. Future House locations and placement of a basement with fixtures would dictate whether a pump would be necessary on the prospective d/f.

As a result of these studies, it is my opinion that the soils in the area of the borings meet the requirements established by the Virginia Department of Health Regulations, and there is enough area for the installation of a subsurface, conventional drainfield suitable for at least a 300 GPD system.

Thank You,...Please contact me if you have any questions or if I can be of further assistance.

Sincerely,

Ron Maye Roger Maxie, Aose #1940001296

and Soil Evaluation Report

VDH Use Only
HDIN:

	General Information	
Date: 2/13/2024 Kirt Sharpe	Patrick Phone: 919-672-0	County Health Department
Owner Address: 4215 Chippenhan	n Court, Graham, NC 27253	
Property Address: same		
Tax Map/GPIN #: 4711-4-83		Block: Lot:
Subdivision:	A THE PROPERTY OF THE PARTY OF	The second discount of the second of the sec
	Soil Information Summary	
Position in landscape satisfactory:	■ Yes □ No Describe landscape	position: upland sideslope
2 Slope: 17 %		
3. Depth to rock/impervious strata:	Maxin. Minin.	Not observed
A Free Water Present: Tyes No	o Range in inches:	
1 -toutable (ore	av mottling or gray color): inche	es Not observed
6. Soil percolation rate estimated:	Yes No Estimated rate: 4	min/in at 40 inches depth
Texture Group: 🗆 I		
7. Percolation test performed: TY	es No If yes, provide additional d	lata on percolation test results.
Boger	r Maxie. Aose1940001296	
Signature:	for Murie	
Site approved: footprint	(describe dispersal area, e	e.g. absorption trenches) dispersing
primary (proposed lev	vel of treatment at time of evaluation)	to be placed at 40 (inches) depth a
		feet of absorption area for primary and
reserve (if applicable).		
Site disapproved: Reasons for re	ejection (check all that apply)	
	ubject to flooding or periodic saturation	on.
2. Insufficient depth of su	itable soil over hard rock.	
	itable soil to seasonal water table.	
4. Rates of absorption too	stow. eptable soil for required absorption as	rea and/or reserve area
6. Proposed system too cle	ose to well.	ica, and/or reserve area.
7. Other (specify)		

Date of Evaluation: 2/13/2024

Profile Description


SOIL EVALUATION REPORT

Property ID: 4711-4-83

Where the local health department conducts the soil evaluation the location of profile holes may be shown on the schematic drawing on the construction permit or the sketch submitted with the application. If soil evaluations are conducted by a private Onsite Soil Evaluator or Professional Engineer, location of profile holes and sketch of the area investigated including all structural features (i.e. sewage disposal systems, wells, etc.) within 200 feet of the site and reserve site shall be shown on the reverse side of this page or prepared on a separate page and attached to this form.

Hole # Horizon Depth (Inches)		Depth	See Construction Permit See sketch on reverse side or page attached to Description of color, texture, etc.	
			2.5 YR 3/3 dark red brown TS clay loam	3
1 Ap 0-4			2.5 YR 3/5 dark red blown	3
	AB	4-20	2.5YR 4/8 red loam,	2
Bt1 20-40			2.5 YR 5/8 red loam,	2
	Bt2	40-66	2.5 YH 5/6 Teu loam,	
		0-5	2.5 YR 3/3 dark red brown TS clay loam	3
2	Ap	5-21	2.5YR 3/6 red clay loam	3
	AB	21-41	2.5YR 4/8 red loam,	2
	Bt1		2.5 YR 5/8 red loam,	2
	Bt2	41-62		
		0.5	2.5 YR 3/3 dark red brown TS clay loam	3
3	Ap	0-5 5-20	2.5YR 3/6 red clay loam	3
	AB		2.5YR 4/8 red loam,	2
	Bt1	20-40	2.5 YR 5/8 red loam	2
	Bt2	40-63		
4				
				A 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1





driveway

ex. camper site

Prop. center of footprint

36,37',34" N 80,17',5" W

> prop. footprint

3 lines 60' long 40" deep 36" wide 9' centers gravelless

